WinPDM
Release Notes – Mars 2026

WinPDM ver. 4.3.0

General

Build date: 17 Mars 2026

Software name: WinPDM

Software version: 4.3.0

Purpose of the release

The purpose of this release is to support many WLAN and DECT devices over USB-hubs

Changes

Description of changes relative to version: 4.2.1

This section describes the improvements, changes and the corrected NCRs.

Improvements and corrections

Release info / Solution
Release of UF-2683/WPDM-1249 - Featurephone - Enable communication to more than one port.

Change request (CR)

ID	Release info / Solution
UF-2683/WPDM-1249	Open up for communication to 2 USB-C ports on Charger module with 2 data enabled charging slots. As development with new Modular Charger Concept targeting a Charging Module for dual handsets with data communication to more than one port, this will make it possible to use the Dual Handset Module as programmer in stand alone

Corrected Non Conformity Reports (NCR)

Customer ID	Release info / Solution

	.

Limitations and known issues

Open JDK must be installed

Known issues (priority critical or high):

Jira Reference	Description	Priority	Consequence
WPDM-1238	Application at start up, stuck in "connecting state"	High	WinPDM at start up, stuck in "connecting state" and no portables are shown. This has been observed 1/10. Restarting WinPDM resolves issue
WPDM-1240	During swdl an a71 or a72 got "bricked", stuck in software download pending.	High	This happens around 1/200 swdl. Workaround to remove battery and performe forced swdl.

Supported Windows version

Windows 11 (64-bit) – recommended and tested

For tested USB-Hubs see appendix

Known bugs

In rare occasions, the device is not shown in the device list in WinPDM, if this happens, restart WinPDM to solve the issue.

Sometimes the handset does not appear online after the upgrade or downgrade, and the previous software version is present in the "Software version" section in WinPDM. The problem appears randomly. If this happens, remove and insert the handset into the charger.

Compatibility Information

Downgrade Not recommended. Max downgrade to 4.1.13

Ascom Wireless Solutions
Grimbodalen 2
402 76 Gothenburg
Sweden
Phone: +46 31 55 93 00
www.ascom.com/ws

Appendix. Tested USB-hubs



Ascom Wireless Solutions
Grimbodalen 2
402 76 Gothenburg
Sweden
Phone: +46 31 55 93 00
www.ascom.com/ws